



One Fire-Lite Place  
Northford, CT 06472-1653 USA

203-484-7161  
203-484-1098 Fax

Document #04-03-4FL

DATE: 08/20/04

## Technical Bulletin

### Multi-I/O Modules - CLASS A Operation

Dear Valued Customer,

System Sensor has reported a potential occurrence of a nuisance problem when addressable multi-I/O modules are configured for Class A operation. In normal operation, Fire-Lite Panels periodically perform a remote self-test of the modules to determine if the wiring is open or shorted. Under normal conditions the module would reply that the circuit is intact. Based on the condition discovered by System Sensor, some modules may create a trouble regardless of wire conditions. This will create a corresponding trouble condition at the panel.

The trouble condition is self-restoring and does not affect the functionality of the addressable multi-modules in reporting alarms. This issue is **not** a life safety concern, nor is the product being recalled as not all modules exhibit this problem.

The **only** Fire-Lite part numbers that are affected by this condition are as follows:

- CMF-300-6
- CMF-300-6A (Canadian)
- MMF-300-10
- MMF-300-10A (Canadian)

No specific date code range has been identified. If you need to replace an installed multi-I/O module exhibiting the conditions described in this Technical Bulletin, Fire-Lite Alarms will provide warranty replacements. Please order new modules per your normal ordering procedure. Any defective units should be returned for credit via our standard RMA process.

If you have any questions regarding this product issue, please contact your Fire-Lite Alarms customer service representative at 203-484-7161. We appreciate your cooperation and understanding, and apologize for any inconvenience resulting from this issue.

Sincerely,

A handwritten signature in black ink, appearing to read "Carlos Abreu".

Carlos Abreu  
Outside Vendor Associate Product Manager  
Honeywell Fire Systems Group