



One Fire-Lite Place
Northford, CT 06472-1653 USA

203-484-7161
203-484-1098 Fax

TECHNICAL BULLETIN

5601 Mechanical Heat Detector replaced with 5601P

August 28, 2005

Document FLTB05-08-1

Dear Business Leader:

The 5601 mechanical heat detector, manufactured by System Sensor, will be discontinued and replaced with the 5601P. The 5601P is the same as the 5601, Single Circuit 135° F fixed-temp/rate-of-rise, with the exception that the detector housing has no exterior markings. The 5601P is UL, FM, CSFM and MEA listed. The 5601 will be discontinued September 30, 2005. Thereafter, only orders for the 5601P will be accepted. We appreciate your cooperation during this transition period. In the mean time, should you have any questions regarding this announcement, please feel free to contact your FireLite Customer Service Representative at (203) 484-7161.

Sincerely,

A handwritten signature in black ink that reads "Nick Martello".

Nick Martello
FireLite Marketing Director