

MRP-4424 and 411UDAC Incorrect Documentation

January 28, 2006

Document FLTB06-01-2

The drawing below, page 45 of the MRP-4424 manual is incorrect. The MRP-4424 panel will not transfer any relays on the 4XZMF when output 4 is configured as a supervisory input. We apologize for any inconvenience. Please contact tech support via email at firelite.tech@honeywell.com or call 1-800-627-3473.

Sincerely,



Nick Martello
FireLite Marketing Director

