

TECHNICAL BULLETIN

MS-9200UDLS Talley Screen Removed

January 19, 2007
Document FLTB07-01-1

Dear Business Leader:

Up until recently, Fire-Lite and other fire alarm manufacturers shipped product meeting the eighth edition of the UL-864 standard. With the adoption of the ninth edition standard a deadline for manufacturers to meet these requirements was set for November of 2005. The preliminary standard required the number of fire alarms, troubles and supervisory indications be displayed. With the release of the final standard, the requirement for displaying number and type of alarm was no longer required.

Firelite engineering has removed this feature in version 3.2 panel software. All panels shipped following release of version 3.2 software will no longer present the tally screen and will once again present the first and highest priority alarm. The new software (9200ud32b5.zip) and downloading instructions can be freely downloaded from www.firelite.com/pktools. If customers are unsure about how to perform the download and panel flash memory upgrade, they are advised to contact tech support at **1-800-627-3473** for assistance.

Sincerely,



Nick Martello
FireLite Marketing Director