



HONEYWELL POWER PRODUCTS

12 Clintonville Road
Northford, CT 06472
www.honeywellpower.com

July 24, 2019

Bulletin: IPGSM-4G Activation Failure

Summary of Issue: IPGSM-4G Activation Failure
Level of Urgency: Low
Model Number(s): IPGSM-4G

Dear Valued Customer,

A non-safety issue has been identified with the Honeywell Power Products IPGSM-4G fire alarm communicator. The IPGSM-4G has a limited activation time of 180 days which, if not installed and activated within this timeframe, may prevent the IPGSM-4G from registering with AlarmNet or AT&T.

The IPGSM-4G has recently been discontinued and replaced with the HWF2V-COM LTE fire alarm communicator. In the event that you experience issues with activating the IPGSM-4G and the product is still under warranty, Honeywell Power Products recommends returning existing stock for replacement with the HWF2V-COM at your earliest convenience.

If you have an IPGSM-4G that is unable to be activated, please call Honeywell Power Products technical support at 1-877-477-7697 to request an RMA. Once the RMA is received, clearly indicate in the Description field that the “unit will not activate”. Honeywell Power Products will honor its warranty return policy and any IPGSM-4G that is unable to be activated and is still within its warranty period should be returned to the original place of purchase for credit.

We appreciate your business and continued support of Honeywell Power Products.